



920K

Humidity & Temperature Meter

Specifications	Range	Resolution	Accuracy
Ambient Temperature / Wet Bulb Temperature / Dew-Point Temperature	-20 ~ 0°C	0.1°C	±1.0°C (0 ~ 45°C)
	0 ~ 60°C	0.01°C	±1.5°C (-20 ~ 0°C, 45 ~ 60°C)
	-4 ~ 0°F	0.1°F	±2.0°F (32 ~ 113°F)
	0 ~ 99.99°F	0.01°F	±2.7°F (-4 ~ 32°F, 113 ~ 140°F)
	100 ~ 140°F	0.1°F	
Humidity	0 ~ 100% RH	0.1%	±3.0% RH (20 ~ 80%) ±4.0% RH (0 ~ 20%, 80 ~ 100%)
Auto Ranging	Yes		
Refresh Rate	3 Times / Second		
Unit	°C / °F Selectable		
Comfort Indicator	Yes		
Data Hold	Yes		
Backlight	Yes		
Auto Power Off	Yes		
Low Battery Indicator	Yes		
Power	1.5V AAA x 2 Batteries		
Operating Altitude	< 2000m		
Operating Temperature	-10°C ~ +50°C		
Storage Temperature	-20°C ~ +60°C		
Operating Humidity	< 80% RH		
Weight	90gms Including Battery (approx.)		
Dimension	155 x 40 x 27mm (approx.)		
Accessories	Carrying Case, Inst. Manual, 1.5V AAA x 2 Batteries (Installed)		



930K

Lux Meter

Specifications	Range	Resolution	Accuracy
Lux / Fc	0 ~ 20.00	0.01	±(3% + 2)
	20.00 ~ 200.0	0.1	
	200.0 ~ 2000	1.0	
	2.000K ~ 20.00K	0.01K	
Lux	20.00K ~ 200.0K	0.1K	
Auto Ranging	Yes		
Spectral Measurement Range	320 ~ 730nm		
Response Time	3 Times / Second		
Min / Max	Yes		
Unit	Lux / Fc		
Data Hold	Yes		
Backlight	Yes		
Auto Power Off	Yes		
Low Battery Indicator	Yes		
Power	1.5V AAA x 2 Batteries		
Operating Altitude	< 2000m		
Operating Temperature	-10°C ~ +50°C		
Storage Temperature	-20°C ~ +60°C		
Operating Humidity	< 80% RH		
Weight	110gms Including Battery (approx.)		
Dimension	155 x 40 x 40mm (approx.)		
Accessories	Carrying Case, Inst. Manual, 1.5V AAA x 2 Batteries (Installed)		